

Message

---

**From:** Cirian, Mike [/O=EXCHANGELABS/OU=EXCHANGE ADMINISTRATIVE GROUP (FYDIBOHF23SPDLT)/CN=RECIPIENTS/CN=98D0FD2CBB3F4F25B819C6929E18D08D-CIRIAN, MIKE]  
**Sent:** 10/11/2018 2:10:18 PM  
**To:** Coan, Sean [CoanSM@cdmsmith.com]  
**CC:** Gunnar Emilsson [EmilssonGR@cdmsmith.com]  
**Subject:** RE: CFAC Daily Activities - 10/10/2018

Thank you

Mike Cirian, PE  
Libby On-site Project Manager  
US EPA  
108 East 9th Street  
Libby, MT 59923  
(406) 293-6194 Office

---

**From:** Coan, Sean [mailto:CoanSM@cdmsmith.com]  
**Sent:** Wednesday, October 10, 2018 7:28 PM  
**To:** Cirian, Mike <Cirian.Mike@epa.gov>  
**Cc:** Gunnar Emilsson <EmilssonGR@cdmsmith.com>  
**Subject:** Re: CFAC Daily Activities - 10/10/2018

Hi Mike,

The following summarizes field oversight activities for 10/10/2018:

- \* Flow transects were collected at CFSWP-025, and -044.
- \* Sediment, surface water, and porewater samples were collected at CFSWP-014, -025, and -044.
- \* Two groundwater sampling crews collected samples at 6 wells (no oversight performed).
- \* Rinsate from the porewater probe was sampled.

No issues were noted. Feel free to get a hold of me if you have any questions or would like to discuss.

Thanks very much,

Sean M. Coan, PG | Project Manager/Geologist | CDM Smith | 50 West 14th Street, Suite 200 | Helena, MT 59601 |  
Direct: 406.441.1463 | Cell: 509.336.5691 | [coansm@cdmsmith.com](mailto:coansm@cdmsmith.com) | [cdmsmith.com](http://cdmsmith.com)